



cmpdi
A Mini Ratna Company



Ref. No. R1-1/HoD (E) /Repair /mud pump / 20-21/ 44-88

Date 16.1.2024

NOTICE INVITING QUOTATIONS

Sealed Quotations are invited from the reputed Work Shops for repairing of GPS125 Mud pump of Dharma sub camp, CMPDI, RI-1, Asanasol. The details of repairing is furnished below.

Sl no	Description of spare parts for repairing /replacement	QTY	Amount
1	Jack shaft with pinion & spacer	03 nos	
2	Side plate of jack shaft	01 no	
3	Cross head side cover 8" x 5 x 1/2 " making	01 no	
4	Valve insert cover making	05 nos	
5	Suction side bucket cover making	01 no	
6	Piston rod flange	01 no	
7	Coupling	02 nos	
8	Propellor shaft	02 nos	
9	Propellor cross	02 sets	
10	Cross flange	02nos	
11	Diesel tank with connections		
12	Clutch servicing		
13	Electrical job		
14	Assembly and fitting charges		
	Total		
	GST		
	Grand total		

P.T.O.



cmpdi
A Mini-Rabia Company

19
YEAR
CEL
THE

General terms & Co.

1) Parties shall submit: GST Regn. No (Photocopy or PAN No (Photocopy or
2) **Delivery:** The repaired pump
receipt of work order CMPDI
3) **Inspection:** The repaired pump
Camp , RI-1, Asansol. There
4) **Guarantee:** There is a warranty of 6 months from the date of delivery. Any defects in the
5) **Payment:** The payment shall be made in RTGS mode after delivery of the pump.

NIQ can be obtained from 16.01.2021 to 22.01.2021 the Office website -- www.cmpdi.co.in between 10 Offers will be opened by in Last date CMPDI RI-I in presence of repairing co

The management reserves the right of the attending
all the parties without assigning any reason.

Sub Camp 1 Asansol, Notice Board, Dharuhera





cmpdi
A Mini Ratna Company



सेन्ट्रल माईन प्लानिंग एंड डिजाइन इन्स्टीट्यूट लिमिटेड
(कोल इंडिया लिमिटेड की अंतर्गती कंपनी / भारत सरकार का एक लोक उत्तर्पाता)
गोन्दवाना प्लैस, कांके रोड, रांची - 834 031, झारखण्ड (भारत)
CORPORATE IDENTITY NUMBER - U14292TH1975GOI001223
कोरोडीय संस्थान-१, वेस्ट एंड, जी.टी. रोड, आसनसोला-७१३३०४
Regional Institute-1, West End, G.T. Road, Asansol-713304

PAGE-02

General terms & conditions are as under:-

- 1) Parties shall submit:
- i) GST Regn. No (Photocopy of certificate) duly signed
- ii) PAN No (Photocopy of certificate) duly signed
- 2) **Delivery:** The repaired pump assembly should be delivered in 07days from the date of receipt of work order CMPDI, RI-1, Asansol.
- 3) **Inspection:** The repaired pump will be inspected by representative of OIC Dharma Sub Camp ,RI-1,Asansol. There will be no compromise with regard to quality.
- 4) **Guarantee /Warranty:** Guarantee/Warranty shall stand for three months from the date of delivery. Any defects in spare will have to be rectified free of cost during guarantee period.
- 5) **Payment:** The payment shall be made by Finance Deptt. of CMPDI, RI-1 Asansol though RTGS mode after delivery the repaired truck against bill/challan in triplicate.

NIQ can be obtained from the Office of Manager (Geology), CMPDI, RI-I in any working day from 16.01.2021 to 22.01.2021 between 10.30 AM to 1.00 PM. It may also be downloaded from CMPDI website -- www.cmpdi.co.in Last date of submission of the quotation on 22.01.2021 upto 3.00 P.M. Offers will be opened by repairing committee on 22.01.2021 at 4.00 PM in Mini Conference Hall, CMPDI RI-I in presence of the attending bidders.

The management reserves the right to accept or reject any or all offers of any party or all the parties without assigning any reason whatsoever.

69/1/2021
16/1/2021
G.M (Geology)

Phu
16/1/2021

Distribution:

- 1 Notice Board, RI-I, Asansol
2. Notice Board, Dharma /Gourangdi/Mollarpur Sub Camp



फोन नम्बर/Phone No. : 0341-2253504
फैक्स नम्बर/Fax No. : 0341-2250935
ई-मेल/E-mail: rdri1.cmpdi@coalindia.in
वेब साईट/Website: www.cmpdi.co.in