



cmpdi
A Mini Ratna Company



सकृद्विचार
ONE EARTH - ONE FAMILY - ONE FUTURE

सेन्ट्रल माईन प्लानिंग एण्ड डिजाइन इन्स्टीच्यूट लिमिटेड
(कोल इण्डिया लिमिटेड की अनुषंगी कम्पनी / भारत सरकार का एक लोक उपक्रम)
गोन्दवाना प्लेस, कान्के रोड, राँची - 834 031, झारखंड (भारत)
Central Mine Planning & Design Institute Limited
(A Subsidiary of Coal India Limited / Govt. of India Public Sector Undertaking)
Gondwana Place, Kanke Road, Ranchi - 834 031, Jharkhand (INDIA)
CORPORATE IDENTITY NUMBER - U14292TH19756OI001223
क्षेत्रीय संस्थान-१, वेस्ट एण्ड, जी.टी. रोड, आसनसोला-७१३३०४
Regional Institute-1, West End, G.T. Road, Asansol-713304

Ref. No. RI-1/HoD (E) /Repair / truck/2022-23/465-221

Date 06.02.2023

NOTICE INVITING QUOTATIONS

To
M/s _____

Sealed Quotations are invited from the reputed Work Shops for repairing of the TATA Truck No-WB37B-5797 of CMPDI,RI-1,Asansol.The details of repairing of the truck is furnished below.

SL. NO.	PARTICULERS OF REPAIRING OF THE TRUCK	AMOUNT
1	Back side Rt. Side deformed dala post cutting and rewelding with angle.	
2	Back right side dala straightending, all lock welding.	
3	Left side dala post straightening, and welding to base.	
4	Dismantaling of deformed bonnet, repairing by providing flat of 3/4" X1/4 " X6' and refitting.	
5	Both side door door channel making and door stopper repairing.	
6	Mudguard sweep repairing both side by providing sheet of 4' x16"	
7	Both side footrest repairiang by providing sheet , angle etc.	
8	Corroded/rusted cabin roor repairing with sheet.	
9	Cabin back side damaged sheet repairing by providing sheet and angle.	
10	Cabin channel repairing of mounting bolts.	
11	Front both side mudguard repairing by providing sheet.	
12	Right side seat repairing.	
13	Gate lock 02 nos repairing.	
14	02 nos door handle	
15	Looking glass 01 nos .	
16	Bonnet rubber lock 02 pcs repairing.	
17	Air filter top cover repairing and fixing to fitter.	
	GST 18%	
	TOTAL	

General terms & conditions are as under:-

- Parties shall submit:
 - GST Regn. No (Photocopy of certificate) duly signed
 - PAN No (Photocopy of certificate) duly signed
- Delivery:** The repaired truck should be delivered in 10 days from the date of receipt of work order CMPDI,RI-1,Asansol.
- Inspection:** The repaired truck will be inspected by representative of HOD(Geology ,RI-1,Asansol. There will be no compromise with regard to quality.
- Warranty:** Warranty shall stand for three months from the date of delivery. Any defects in spare will have to be rectified free of cost during guarantee period.
- Payment:** The payment shall be made by Finance Deptt. of CMPDI, RI-I Asansol though RTGS mode after delivery of repaired truck to CMPDIL,RI-1 Asansol against bill/challan in triplicate.



cmpdi
A Mini Ratna Company



सेन्ट्रल माईन प्लानिंग एण्ड डिजाइन इंस्टीट्यूट
(कोल इण्डिया लिमिटेड की अनुबंधी कंपनी / भारत सरकार का एक लो
गोन्दवाना प्लेस, कान्के रोड, राँची - 834 031, झारखंड
Central Mine Planning & Design Institute Limited
(A Subsidiary of Coal India Limited / Govt. of India Public Sector Undertaking)
Gondwana Place, Kanke Road, Ranchi - 834 031, Jharkhand (INDIA)
CORPORATE IDENTITY NUMBER - U14292JH1975GOI0012
क्षेत्रीय संस्थान-१, वेस्ट एण्ड, जी.टी. रोड, आसनसोला-७१३३०४
Regional Institute-1, West End, G.T. Road, Asansol-713304

Page-02

NIQ can be obtained from Office of Asstt Manager (E &M), CMPDI, RI-I in any working day from 06.02.2023 to 13.02.2023 between 10.30 AM to 1.00 PM. It may also be downloaded from CMPDI website -- www.cmpdi.co.in Last date of submission of the quotation on 13.02.2023 upto 3.00 P.M. Offers will be opened by reparing committee on 14.02.2023 at 4.00 PM in Mini Conference Hall, CMPDI RI-I in presence of the attending bidders.

The management reserves the right to accept or reject any or all offers of any party or all the parties without assigning any reason whatsoever.

Table 4-h 7/2/23
HOD (Geology)

Distribution:

- 1 Notice Board, RI-I, Asansol
2. Notice Board, Dharma /Madhukunda/Mollarpur Sub Camp