




An ISO 9001: 2015 & ISO 37001: 2016 Certified Company

Ref. No. RI-1/HoD (E) /Repair /Bolero/ 25-26/ 19-31

Date 08.05.2025

To  
M/s \_\_\_\_\_



**NOTICE INVITING QUOTATIONS**

Sealed Quotations are invited from the reputed Work Shops for repairing of the Bolero (Light vehicle) Make Mahindra & Mahindra No- WB44B-3322, of CMPDI, RI-1, Asansol. The details of repairing of the vehicle is furnished below.

L. NO.	PARTICULARS OF REPAIRING /REPLACEMENT	AMOUNT
1	Mobil change-----07 ltrs	
2	Mobil filter-----01 Pc	
3	Diesel filter-----01 set	---
4	Gasket	
5	Air filter-----01pc	
6	Chamber joint	
7	Brake pad assy(front)----01set	
8	Dielsel, Mobil,Air filter changing charges	
9	Front brake pad changing charges and brake adjusting charges	
10	Front wheel alignment	
11	Partial washing of vehicle	
12	Broke silencer pices joining with supports.	
13	Dismantling and refitting by clamps making and fitting.	
14	Right side foot rest repairing by welding with plates	
15	Spring bush -----06pcs	
16	Shocker bush -----08pcs	
17	Front balance balance bush----02pcs	
18	Rear balance bush-----02pcs	
19	Link bush-----04pcs	
20	Link washer-----08pcs	
21	Rear both side spring leaf assy dismantling ,bushes changing and refitting (including gas cutting both sides)	
22	Front balance rod removing, bushes changing and refitting	
23	Differential and gear box oil changing	
24	Front wheel both side wheels greasing charges including grease and oil seal & lock	
25	Glass wiper -----1set	
26	Fitting charges of glass wiper.	
	<b>GST 18%</b>	
	<b>TOTAL</b>	

PTO





An ISO 9001: 2015 & ISO 37001: 2016 Certified Company

Page-02

**General terms & conditions are as under:-**

- Delivery:** The Bolero van should be delivered in 07days from the date of receipt of work order CMPDI, RI-1, Asansol.
- Inspection:** The van will be inspected by representative of HOD (Geology), RI-1, Asansol. There will be no compromise with regard to quality.
- Warranty:** Warranty shall stand for six months from the date of delivery. Any defects in spare will have to be rectified free of cost during guarantee period.
- Payment:** The payment shall be made by Finance Deptt. of CMPDI, RI-1 Asansol through RTGS mode after delivery the repaired bolero against bill/challan in triplicate.
- Submitted a copy of pan and GST registration certificate.

NIQ can be obtained from the Office of Dy. Manager (E & M), CMPDI, RI-1 in any working day from 09.05.2025 to 15.05.2025 between 10.30 AM to 1.00 PM. It may also be downloaded from CMPDI website -- [www.cmpdi.co.in](http://www.cmpdi.co.in) Last date of submission of the quotation on 15.05.2025 upto 1.00 P.M. Offers will be opened by repairing committee on 15.05.2025 at 3.00 PM in Mini Conference Hall, CMPDI RI-1 in presence of the attending bidders.

The management reserves the right to accept or reject any or all offers of any party or all the parties without assigning any reason whatsoever.

**AVIK  
SEN**

Digitally signed by AVIK SEN  
DN: C=IN, O=CMPDI, OU=EXPLORATION,  
PostalCode=713304, L=ASANSOL, S=WEST  
BENGAL, STREET=REGIONAL INSTITUTE-1  
GT ROAD W ASANSOL, Phone=+919833176617  
Email=avik.sen@coalindia.co.in  
Date: 2023-05-08 10:35:04+05'30'

HOD (Geology)

**Distribution:**

- Notice Board, RI-1, Asansol
- Notice Board, Dharma /Gourangdi/Mollarpur Sub Camp

OTR

एकांकीकरण विभाग  
संपर्क संख्या: 0341-2253504  
संस्थान का नाम: राज्यीय खनन की कंपनी  
संस्थान का संकेतन: 10150 001

